

VALLEY

Decode that model number

That cryptic “model number with no numbers” found on Valley tables since 1986 or so isn’t some sort of confidential secret. This sheet will help you crack the code – no decoder ring needed!! The information given here is thought to be accurate, but we suspect it’s incomplete. If you find something not listed here on a VALLEY COIN POOL TABLE model number combination, drop us a line at parts@valley-dynamo.com so we can complete, refine and correct this guide.

CP B DR CDC -

FIRST TWO LETTERS : The only codes used at present are

CP = “Coin Push chute”

BP = “Panther Black Cat w/Coin Push Chute”

DB = “Dollar Bill Acceptor”

DC = “Panther Black Cat w/Dollar Bill Acceptor”

Since going to this format there were other codes used

CT = The Valley “Contemporary” Image Series Table

WT = The Valley “Country” Image Series Table

TT = The Valley “Traditional” Image Series Table

LA = The Valley “Cat” Standard Table

BB = Black Cat tables

UL = Valley Leopard

THIRD LETTER : Size of table

A = 101” / 8-foot

B = 93” / 7-foot

C = 88” / 6½-foot

We are no longer producing these sizes of tables, but when we did...

D = 85” / 6-foot

E = 78” / 6-foot

9 = 110” / 9-foot

FOURTH AND FIFTH LETTER : Finish of Table

DR = Cheyenne Leather (Panther, Panther ZD-X)

CH = Biltmore Cherry or Victorian Cherry (Cougar)

AJ = Charcoal Chromatic (Black Cat)

RG = Graphite (Black Cat)

FA = Charcoal Chromatic w/Powder coated Hardware (Black Cat)

JM = Jewel Mahogany (ZD-8, Great 8)

BS = Taj Teak (ZD-7)

SA = Summit Ash (ZD-6)

SM = Sable Maple (ZD-5)

DZ= Classic Mahogany (ZD-4)

PB = Anigre suede finish woodgrain ("The Cat")

NEXT THREE LETTERS : Acceptance of payment

CDC – ESD Push Chute

MEI – MEI Bill Acceptor

And these codes used on past tables

ICT – ICT Bill Acceptor

JCM – JCM Bill Acceptor

WDC – Greenwald Push Chute

NUMBERS IMMEDIATELY FOLLOWING : Build Sequence number

- As noted above, this guide is incomplete. While the listed information is strongly suspected to be correct, this is a new guide and time and customer feedback will help us work out the bugs. Also, this refers to how tables left our factory and do not account for a laminate or bill acceptor switch by a former owner.